Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080194-9

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA 8, CALIF.

No 128148

RECEIVED FROM

DATE REC'D 2-12-47

P. O. NO

VENDOR PACKING SLIP NO

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W. O. NO. / S. O. NO.
	322	000000	220-8	0	0	00	03			

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
1	73625 CHST [illegible]	✓		
	SHIP MEMO 85862			

RECEIVED BY

INSPECTED BY (HC)

DATE 2-12

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA 8, CALIF.

No 128144

RECEIVED FROM

DATE REC'D 2-12-47

P. O. NO

VENDOR PACKING SLIP NO

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W. O. NO. / S. O. NO.
	322	000000	82045	0	0	00	00			

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
2	73999 CLAMP TUBE ASS'Y	2 ✓		
	MFR S.D.			
	SHIP MEMO 85859			

RECEIVED BY

INSPECTED BY [illegible]

DATE 2-12-47

REJECTS RETURNED ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080194-9